



Repair - BRANCH V Sept 06, 2023	
Wildfire Perimeter	Branch Break
Contained Fire Edge	Drop Point
Uncontained Fire Edge	Staging Area
Completed Dozer Line	Dip Site
Completed Hand Line	Helispot
Completed Mixed Construction Line	Unimproved Landing Area
Completed Road as Line	Hot Spot - Spot Fire
Other	Value at Risk
Access or Improved Road	Other
Road Repair	Internet Access
Division Break	Repeater
Hazard	Campground
Water Source	Trailhead
Gate	Lookout - Permanent
National Forest Boundary	Highway
Non-FS Lands w/in Forest Bdy.	Light Duty - Paved
Ranger District	Light Duty - Gravel
Wilderness Area	Light Duty - Dirt
National Wild and Scenic River	Unimproved
County	Trail
Forest Service Facility	Trail - Nat Rec/Scenic/Historic
Roadside Park	

Suppression Repair
BRANCH V
 Happy Camp Complex
 CA-KNF-007022
 Sept 06, 2023

Repair Status		Repair Points	
In Use - Fire Management	In Use - Fire Management	Water Development or Draft Site	Structure Wrap
Needs Assessment	Needs Assessment	Road Repair	Repair Point
Repair Needed	Repair Needed	Hazard Tree	Dozer Push
In Progress	In Progress	Culvert	Clean Up Area
Completed - Ready for Inspection	Completed - Ready for Inspection	Completed - Inspected	No Repair - See Comments
Completed - Inspected	Completed - Inspected	No Repair - See Comments	
No Repair Needed	No Repair Needed		
Other - See Comments	Other - See Comments		

0 0.25 0.5 1
Miles

PCS: NAD 1983 UTM Zone 10N Scale: 1:20,000 Contour Interval: 80 ft

Repair BRANCH V
 Sept 06, 2023