



Repair BRANCH XXX-N
Sept 06, 2023

Wildfire Perimeter	Division Break	Water Source	Lookout - Permanent
Contained Fire Edge	Drop Point	Gate	Highway
Uncontained Fire Edge	Staging Area	National Forest Boundary	Light Duty - Paved
Completed Dozer Line	Helispot	Non-FS Lands w/in Forest Body	Light Duty - Gravel
Completed Hand Line	Unimproved Landing Area	Ranger District	Light Duty - Dirt
Completed Road as Line	Lookout	National Wild and Scenic River	Unimproved
Other	Other	County	Trail
Access or Improved Road	Gate	Timber Lands - AKF	Footbridge
Repair Line	Bridge	Forest Service Facility	Campground
Road Repair	Hazard		

**Suppression Repair
BRANCH XXX North**
Happy Camp Complex
CA-KNF-007022
Sept 06, 2023

Repair Status		Repair Points	
In Use - Fire Management	In Use - Fire Management	Water Development or Draft Site	Stream Crossing
Needs Assessment	Needs Assessment	Road Repair	Repair Point
Repair Needed	Repair Needed	Dozer Push	Clean Up Area
In Progress	In Progress		
Completed - Ready for Inspection	Completed - Ready for Inspection		
Completed - Inspected	Completed - Inspected		
No Repair Needed	No Repair Needed		
Other - See Comments	Other - See Comments		

Scale: 1:17,000 Contour Interval: 80 ft.

PCS: NAD 1983 UTM Zone 10N

Repair BRANCH XXX-N
Sept 06, 2023