



Repair BRANCH V-S Sept 07, 2023	
Wildfire Perimeter	Staging Area
Contained Fire Edge	Dip Site
Uncontained Fire Edge	Helispot
Completed Dozer Line	Unimproved Landing Area
Completed Hand Line	Hot Spot - Spot Fire
Completed Mixed Construction Line	Value at Risk
Completed Road as Line	Other
Other	Internet Access
Access or Improved Road	Repeater
Division Break	Hazard
Drop Point	Water Source
Gate	Forest Service Facility
Roadside Park	Campground
Trailhead	Lookout - Permanent
Light Duty - Paved	Light Duty - Gravel
Light Duty - Dirt	Unimproved
Trail	Trail - Nat Rec/Scenic/Historic
National Forest Boundary	Non-FS Lands w/in Forest Bdy.
Ranger District	Wilderness Area
National Wild and Scenic River	County
Bureau of Indian Affairs	

**Suppression Repair
BRANCH V SOUTH**
Happy Camp Complex
CA-KNF-007022
Sept 07, 2023

Repair Status		Repair Features	
In Use - Fire Management	In Use - Fire Management	Water Development or Draft Site	Structure Wrap
Needs Assessment	Needs Assessment	Road Repair	Repair Point
Repair Needed	Repair Needed	Hazard Tree	Dozer Push
In Progress	In Progress	Culvert	Clean Up Area
Completed - Ready for Inspection	Completed - Ready for Inspection	Road Repair	
Completed - Inspected	Completed - Inspected		
No Repair Needed	No Repair Needed		
Other - See Comments	Other - See Comments		

0 0.25 0.5 1 Miles

UAS
Northern Rockies
INCIDENT MANAGEMENT TEAM

Repair BRANCH V-S
Sept 07, 2023

NAD 1983 UTM Zone 10N
Contour Interval: 80 ft.