



# BRANCH V

Div L

Div K

Div H

Div J

Repair BRANCH V-N Sept 08, 2023	
Happy Camp Complex	Drop Point
Contained Fire Edge	Camp
Uncontained Fire Edge	Mobile Retardant Base
Completed Dozer Line	Campground
Completed Hand Line	Trailhead
Completed Mixed Construction Line	Unimproved Landing Area
Completed Road as Line	Value at Risk
Other	Other
Access or Improved Road	Internet Access
Historical Dozer Line	Hazard
Division Break	Water Source
Gate	Ranger District Office
Trail - Nat Rec/Scenic/Historic	Roadside Park
Footbridge	Campground
National Forest Boundary	Trailhead
Non-FS Lands w/in Forest Bdy	Unimproved Landing Area
National Wild and Scenic River	Value at Risk
County	Other
Bureau of Indian Affairs	Internet Access
State of California	Hazard
City	Water Source
Unimproved	Ranger District Office
Trail	Roadside Park

## Suppression Repair BRANCH V NORTH Happy Camp Complex CA-KNF-007022

Sept 08, 2023

Repair Status		Repair Features	
In Use - Fire Management	In Use - Fire Management	Water Development or Draft Site	Structure Wrap
Needs Assessment	Needs Assessment	Road Repair	Repair Point
In Progress	In Progress	Landing or Log Deck	Hazard Tree
Completed - Ready for Inspection	Completed - Ready for Inspection	Dozer Push	Culvert
Completed - Inspected	Completed - Inspected	Clean Up Area	
No Repair Needed	No Repair Needed		
Other - See Comments	Other - See Comments		

0 0.5 1  
Miles

Repair BRANCH V-N  
Sept 08, 2023

NAD 1983 UTM Zone 10N  
Contour Interval: 80 Ft.