



Repair BRANCH V-S		Repair BRANCH V-S	
	Happy Camp Complex		Drop Point
	Contained Fire Edge		Gate
	Uncontained Fire Edge		Forest Service Facility
	Completed Dozer Line		Roadside Park
	Completed Hand Line		Campground
	Completed Mixed Construction Line		Trailhead
	Completed Road as Line		Lookout - Permanent
	Other		Lookout - Light Duty - Paved
	Access or Improved Road		Lookout - Light Duty - Gravel
	Historical Dozer Line		Lookout - Light Duty - Dirt
	Division Break		Water Source
	Dip Site		Gate
	Helispot		Unimproved
	Unimproved Landing Area		Trail
	Value at Repeater		Trail - Nat Rec/Scenic/Historic
	Repeater		National Forest Boundary
	Hazard		Ranger District
			Non-FS Lands w/in Forest Body
			Wilderness Area
			National Wild and Scenic River
			County
			Bureau of Indian Affairs

Suppression Repair
BRANCH V SOUTH
 Happy Camp Complex
 CA-KNF-007022
 Sept 08, 2023

Repair Status		Repair Status	
	In Use - Fire Management		Needs Assessment
	Needs Assessment		Repair Needed
	In Progress		In Progress
	Completed - Ready for Inspection		Completed - Ready for Inspection
	Completed - Inspected		Completed - Inspected
	No Repair Needed		No Repair Needed
	Other - See Comments		Other - See Comments

Repair Features	
	Water Development or Draft Site
	Structure Wrap
	Road Repair
	Repair Point
	Hazard Tree
	Dozer Push
	Culvert
	Clean Up Area
	Repair Line
	Road Repair

MAP DATE: 08/2023
 UTM ZONE: 10N
 CONTOUR INTERVAL: 80 FT.

Repair BRANCH V-S
 Sept 08, 2023