



Repair BRANCH XXX-S
Sept 08, 2023

<ul style="list-style-type: none"> Happy Camp Complex Contained Fire Edge Uncontained Fire Edge Completed Dozer Line Completed Hand Line Completed Road as Line Other Access or Improved Road Historical Dozer Line Division Break 	<ul style="list-style-type: none"> Drop Point Aviation Check Point Dip Site Helispot Sling Site Other Repeater Gate Forest Service Facility Campground 	<ul style="list-style-type: none"> Trailhead Light Duty - Paved Light Duty - Gravel Light Duty - Dirt Light Duty - Unspecified Composition Unimproved Trail Trail - Nat Rec/Scenic/Historic National Forest Boundary 	<ul style="list-style-type: none"> Ranger District Non-FS Lands w/in Forest Body Wilderness Area National Wild and Scenic River County Bureau of Land Management Timber Lands - Ecotrust Forest Management Timber Lands - AKF
--	--	---	---

Suppression Repair BRANCH XXX South
Happy Camp Complex
CA-KNF-007022
Sept 08, 2023

Repair Status		Repair Features	
<ul style="list-style-type: none"> In Use - Fire Management Needs Assessment In Progress Completed - Ready for Inspection Completed - Inspected No Repair Needed Other - See Comments 	<ul style="list-style-type: none"> In Use - Fire Management Needs Assessment Repair Needed In Progress Completed - Ready for Inspection Completed - Inspected No Repair Needed Other - See Comments 	<ul style="list-style-type: none"> Water Development or Draft Site Structure Wrap Stream Crossing Repair Point Dozer Push Culvert Road Repair 	<ul style="list-style-type: none"> Forest Service UAS Northern Rockies Incident Management Team

Scale: 0 to 1 Miles

Map: 1983 UTM Zone 10N
Contour Interval: 80 ft.

Repair BRANCH XXX-S
Sept 08, 2023