



BRANCH V

Suppression Repair BRANCH V North Happy Camp Complex CA-KNF-007022

Sept 09, 2023

Happy Camp Complex	Division Break	Gate	Unimproved
Contained Fire Edge	Drop Point	Ranger District Office	Trail
Uncontained Fire Edge	Camp	Roadside Park	Trail - Nat Rec/Scenic/Historic
Completed Dozer Line	Mobile Retardant Base	Campground	Footbridge
Completed Hand Line	Helispot	Trailhead	National Forest Boundary
Completed Mixed Construction Line	Unimproved Lading Area	Other	Non-FS Lands w/in Forest Bdy.
Completed Road as Line	Value at Risk	Highway	National Wild and Scenic River
Other	Internet Access	Light Duty - Paved	County
Access or Improved Road	Hazard	Light Duty - Gravel	Bureau of Indian Affairs
Historical Dozer Line	Water Source	Light Duty - Dirt	State of California
		Composition	City

Repair Status	
In Use - Fire Management	In Use - Fire Management
Needs Assessment	Needs Assessment
Repair Needed	Repair Needed
In Progress	In Progress
Completed - Ready for Inspection	Completed - Ready for Inspection
No Repair Needed	No Repair Needed
Other - See Comments	Other - See Comments

Repair Features
Water Development or Draft Site
Structure Wrap
Stream Crossing
Road Repair
Repair Point
Landing or Log Deck
Hazard Tree
Dozer Push
Culvert
Clean Up Area

0 0.25 0.5 1
Miles

MD 1983 UTM Zone 10N Contour Interval: 80 ft.

Repair - Branch V-N
 Sept 09, 2023