



Repair - Branch XXX-N Sept 09, 2023	
	Happy Camp Complex
	Contained Fire Edge
	Uncontained Fire Edge
	Completed Dozer Line
	Completed Fuel Break
	Completed Hand Line
	Completed Road as Line
	Access or Improved Road
	Historical Dozer Line
	Division Break
	Drop Point
	Staging Area
	Helispot
	Unimproved Landing Area
	Lookout
	Other
	Gate
	Bridge
	Hazard
	Water Source
	Gate
	Forest Service Facility
	Campground
	Lookout - Permanent
	Light Duty - Paved
	Light Duty - Gravel
	Light Duty - Dirt
	Unimproved
	Trail
	Footbridge
	National Forest Boundary
	Ranger District
	Non-FS Lands w/in Forest Bdy.
	National Wild and Scenic River
	County
	Bureau of Indian Affairs
	Timber Lands - AKF

**Suppression Repair
BRANCH XXX North**

Happy Camp Complex
CA-KNF-007022

Sept 09, 2023

Repair Status	
	In Use - Fire Management
	Needs Assessment
	In Progress
	Completed - Ready for Inspection
	Completed - Inspected
	No Repair Needed
	Other - See Comments
	In Use - Fire Management
	Needs Assessment
	In Progress
	Completed - Ready for Inspection
	Completed - Inspected
	No Repair Needed
	Other - See Comments

Repair Features	
	Water Development or Draft Site
	Stream Crossing
	Road Repair
	Repair Point
	Landing or Log Deck
	Dozer Push
	Clean Up Area
	Repair Line
	Road Repair

0 0.25 0.5 1 Miles

Repair - Branch XXX-N
Sept 09, 2023

MD 1983 UTM Zone 10N Contour Interval: 80 ft.