



BRANCH V

Suppression Repair BRANCH V North Happy Camp Complex CA-KNF-007022

Sept 10, 2023

Repair - Branch V-N
Sept 10, 2023

<ul style="list-style-type: none"> Happy Camp Complex Contained Fire Edge Uncontained Fire Edge Completed Dozer Line Completed Hand Line Completed Mixed Construction Line Completed Road as Line Other Access or Improved Road Historical Dozer Line 	<ul style="list-style-type: none"> Division Break Drop Point Camp Mobile Retardant Base Helispot Value at Risk M Other Internet Access Hazard Water Source Gate 	<ul style="list-style-type: none"> Ranger District Office Campground Trailhead Roadside Park Highway Light Duty - Paved Light Duty - Gravel Light Duty - Dirt Light Duty - Unspecified Composition Unimproved 	<ul style="list-style-type: none"> Trail Trail - Nat Rec/Scenic/Historic Footbridge National Forest Admin. Boundary Non-FS Lands w/in Forest Body National Wild and Scenic River County Bureau of Indian Affairs State of California City
---	---	--	---

Repair Status		Repair Features	
<ul style="list-style-type: none"> In Use - Fire Management Needs Assessment Repair Needed In Progress Completed - Ready for Inspection Completed - Inspected No Repair Needed Other - See Comments 	<ul style="list-style-type: none"> In Use - Fire Management Needs Assessment Repair Needed In Progress Completed - Ready for Inspection Completed - Inspected No Repair Needed Other - See Comments 	<ul style="list-style-type: none"> Water Development or Draft Site Structure Wrap Stream Crossing Road Repair Repair Point Landing or Log Deck Hazard Tree Dozer Push Culvert Clean Up Area 	<ul style="list-style-type: none"> Event Point Event Line

0 0.25 0.5 1
Miles

MD 1983 UTM Zone 10N Contour Interval: 80 Ft.

Repair - Branch V-N
Sept 10, 2023