



Repair - Overview		Repair Status	
Happy Camp Complex	Completed Hand Line	In Use - Fire Management	Needs Assessment
Smith River Complex	Completed Mixed Construction Line	Repair Needed	In Progress
SRF Lightning Complex	Completed Road as Line	Completed - Ready for Inspection	Completed - Inspected
Other 2023 Fires > 10 ac	Other	No Repair Needed	Other - See Comments
Contained Fire Edge	Access or Improved Road	In Use - Fire Management	Needs Assessment
Uncountained Fire Edge	Division Break	Repair Needed	In Progress
Completed Dozer Line	Branch Break	Completed - Ready for Inspection	Completed - Inspected
Completed Fuel Break	Drop Point	No Repair Needed	Other - See Comments
Camp	Camp		
Staging Area	Dip Site		
Aviation Check Point	Mobile Retardant Base		
Dip Site	Helibase		
Mobile Retardant Base	Sling Site		
Helibase	Lookout		
Sling Site	Hot Spot - Spot Fire		
Lookout			
Hot Spot - Spot Fire			
Value at Risk	Gate		
Other	Ranger District Office		
Gate	Forest Service Facility		
Bridge	Campground		
Internet Access	Picnic Area		
Repeater	Trailhead		
Hazard	Roadside Park		
Water Source	Lookout/Permanent		
Restricted Water Source	Footbridge		
Highway			
National Forest	Bureau of Land Management		
Admin. Boundary	Bureau of Indian Affairs		
Ranger District Boundary	State of California		
Non-FS Lands w/in Forest Bdy	City		
Wilderness Area	The Nature Conservancy		
National Wild and Scenic River	Timber Lands - Ecotrust Forest Management		
National Rec/Scenic Area	Timber Lands - AKF		
County			

Suppression Repair OVERVIEW

Happy Camp Complex CA-KNF-007022

Sept 10, 2023

EVENT Point		EVENT Line		Repair Features	
In Use - Fire Management	Repair Needed	In Use - Fire Management	Repair Needed	Water Development or Draft Site	Hazard Tree
Repair Needed	In Progress	Needs Assessment	In Progress	Structure Wrap	Dozer Push
In Progress	Completed - Ready for Inspection	In Progress	Completed - Ready for Inspection	Stream Crossing	Culvert
Completed - Ready for Inspection	Completed - Inspected	Completed - Ready for Inspection	Completed - Inspected	Road Repair	Clean Up Area
Completed - Inspected	No Repair Needed	Completed - Ready for Inspection	No Repair Needed	Resource Location	Repair Point
No Repair Needed	Other - See Comments	Other - See Comments	Other - See Comments	Repair Point	Repair Line
Other - See Comments		Other - See Comments		Landing or Log Deck	Road Repair

0 0.5 1 2 3 4 Miles

NAD 1983 UTM Zone 10N Contour Interval: 400 ft.

Repair - Overview
Sept 10, 2023