



BRANCH V

Div E/H

Div J

Div C

**Suppression Repair
BRANCH V South**
Happy Camp Complex
CA-KNF-007022

Sept 12, 2023

Happy Camp Complex	Access or Improved Road	Hazard	Light Duty - Dirt
Other 2023 Fires > 10 ac.	Historical Dozer Line	Water Source	Unimproved
Contained Fire Edge	Drop Point	Gate	Trail
Uncontained Fire Edge	Staging Area	Forest Service Facility	Trail - Nat Rec/Scenic/Historic
Completed Dozer Line	Dip Site	Campground	National Forest Admin. Boundary
Completed Fuel Break	Helispot	Trailhead	Ranger District Boundary
Completed Hand Line	Hot Spot - Spot Fire	Roadside Park	Non-FS Lands w/in Forest Bdy.
Completed Mixed Construction Line	Value at Risk	Lookout - Permanent	Wilderness Area
Completed Road as Line	Other	Highway	National Wild and Scenic River
Other	Internet Access	Light Duty - Paved	County
	Repeater	Light Duty - Gravel	Bureau of Indian Affairs

Repair Status	Repair Features
In Use - Fire Management	Water Development or Draft Site
Needs Assessment	Structure Wrap
Repair Needed	Road Repair
In Progress	Repair Point
Completed - Ready for Inspection	Landing or Log Deck
Completed - Inspected	Hazard Tree
No Repair Needed	Dozer Push
Other - See Comments	Culvert
	Clean Up Area
	Repair Line

Scale: 0 0.25 0.5 1 Miles

MD 1983 UTM Zone 10N Contour Interval: 80 ft.

Repair - Branch V-S
Sept 12, 2023