


# Suppression Repair BRANCH XXX South

## Happy Camp Complex CA-KNF-007022



Sept 13, 2023

Repair - Branch XXX-S Sept 13, 2023	
Happy Camp Complex	Campground
Contained Fire Edge	Trailhead
Uncontained Fire Edge	Light Duty - Paved
Completed Dozer Line	Light Duty - Gravel
Aviation Check Point	Light Duty - Dirt
Dip Site	Light Duty - Unspecified Composition
Helispot	Unimproved
Sling Site	Trail
Other	Trail - Nat Rec/Scenic/Historic
Repeater	National Forest Admin. Boundary
Gate	Ranger District Boundary
Forest Service Facility	Non-FS Lands w/in Forest Bdy.
	Wilderness Area
	National Wild and Scenic River
	County
	Bureau of Land Management
	Timber Lands - Ecotrust Forest Management
	Timber Lands - AKF

Repair Status		Repair Features	
In Use - Fire Management	In Use - Fire Management	Water Development or Draft Site	Structure Wrap
Needs Assessment	Needs Assessment	Stream Crossing	Resource Location
In Progress	In Progress	Repair Push	Dozer Push
Completed - Ready for Inspection	Completed - Ready for Inspection	Culvert	Road Repair
Completed - Inspected	Completed - Inspected		
No Repair Needed	No Repair Needed		
Other - See Comments	Other - See Comments		



0 0.25 0.5 1 Miles

Repair - Branch XXX-S  
Sept 13, 2023