



Repair - DTAG
Sept 13, 2023

<ul style="list-style-type: none"> Happy Camp Complex SRF Lightning Complex Contained Fire Edge Uncontained Fire Edge Division Break Ranger District Office Campground Trailhead 	<ul style="list-style-type: none"> Roadside Park Lookout - Permanent Gate Highway Light Duty - Paved Light Duty - Gravel Light Duty - Dirt Light Duty - Unspecified Composition 	<ul style="list-style-type: none"> Unimproved River Trail Trail - Nat Rec/Scenic/Historic Footbridge National Forest Admin. Boundary Ranger District Boundary Wilderness Area 	<ul style="list-style-type: none"> National Wild and Scenic County Non-FS Lands w/in Forest Bdy Bureau of Land Management Bureau of Indian Affairs State of California 	<ul style="list-style-type: none"> City The Nature Conservancy <all other values> Timber Lands - AKF Timber Lands - Ecotrust Forest Management 	<ul style="list-style-type: none"> DTAG Features DTAG Road Landing or Log Deck Hazard Tree
--	---	---	--	---	--

Suppression Repair Danger Tree Abatement Group

Happy Camp Complex
CA-KNF-007022
Sept 13, 2023

DTAG Repair Status - Points

- In Use - Fire Management
- Needs Assessment
- Repair Needed
- In Progress
- Completed - Ready for Inspection
- Completed - Inspected
- No Repair Needed
- Other - See Comments

DTAG Repair Status - Roads

- In Use - Fire Management
- Needs Assessment
- Repair Needed
- In Progress
- Completed - Ready for Inspection
- Completed - Inspected
- No Repair Needed
- Other - See Comments

DTAG Cult. Clearance - Points

- Cult. Survey Needed
- Cult. Cleared

DTAG Cult. Clearance - Roads

- Cult. Survey Needed
- Cult. Cleared

Repair Status	DTAG Roads (miles)	Hazard Trees	Landings/Log Decks
TOTAL	62.7	20	67
Completed	0	0	0
In Progress	0	0	0
Repair Needed	62.7	20	67
No Repair Needed	0	0	0

0 0.5 1 2 Miles

Repair - DTAG