



<ul style="list-style-type: none"> Happy Camp Complex Contained Fire Edge Uncontained Fire Edge Completed Dozer Line Completed Hand Line Completed Mixed Construction Line Completed Road as Line Other Access or Improved Road Historical Dozer Line 	<ul style="list-style-type: none"> Division Break Drop Point Camp Mobile Retardant Base Helispot Lookout Value at Risk Other Hazard Water Source Gate 	<ul style="list-style-type: none"> Ranger District Office Campground Trailhead Roadside Park Highway Light Duty - Paved Light Duty - Gravel Light Duty - Dirt Light Duty - Unspecified Composition Unimproved 	<ul style="list-style-type: none"> Trail Trail - Nat Rec/Scenic/Historic Footbridge National Forest Admin. Boundary Non-FS Lands w/in Forest Bdy. National Wild and Scenic River County Bureau of Indian Affairs State of California City
---	--	--	---

Suppression Repair BRANCH V Middle

Happy Camp Complex CA-KNF-007022

Sept 14, 2023

Repair Status	Repair Status
<ul style="list-style-type: none"> Event Point - Repair Status In Use - Fire Management Needs Assessment Repair Needed In Progress Completed - Ready for Inspection Completed - Inspected No Repair Needed Other - See Comments 	<ul style="list-style-type: none"> Event Line - Repair Status In Use - Fire Needs Assessment Repair Needed In Progress Completed - Ready for Inspection Completed - Inspected No Repair Needed Other - See Comments

Repair Features

- Water Development or Draft Site
- Structure Wrap
- Stream Crossing
- Road Repair
- Repair Point
- Dozer Push
- Culvert
- Clean Up Area

Scale: 0 0.25 0.5 1 Miles

US Forest Service Logo

Northwood Rockwood Incident Management Team Logo

MD 1983 UTM Zone 10N Contour Interval: 80 ft.

Repair - BR V Middle
Sept 14, 2023

Repair - BR V Middle
Sept 14, 2023