



<ul style="list-style-type: none"> Contained Fire Edge Uncountained Fire Edge Completed Dozer Line Completed Hand Line Completed Mixed Construction Line Completed Road as Line Historical Dozer Line Drop Point 	<ul style="list-style-type: none"> Camp Mobile Retardant Base Value at Risk Other Hazard Gate Ranger District Office Forest Service Facility Campground 	<ul style="list-style-type: none"> Highway Light Duty - Paved Light Duty - Gravel Light Duty - Dirt Light Duty - Unspecified Composition Unimproved Trail Trail - Nat Rec/Scenic/Historic National Forest Admin. Boundary 	<ul style="list-style-type: none"> Ranger District Boundary Non-FS Lands w/in Forest Bdy. Wilderness Area National Wild and Scenic River County Bureau of Indian Affairs State of California City The Nature Conservancy
--	--	--	---

Suppression Repair
BRANCH V North
 Happy Camp Complex
 CA-KNF-007022
 Sept 16, 2023

Repair Status	Event Line - Repair Status
<ul style="list-style-type: none"> In Use - Fire Management Needs Assessment Repair Needed In Progress Completed - Ready for Inspection Completed - Inspected No Repair Needed Other - See Comments 	<ul style="list-style-type: none"> In Use - Fire Management Needs Assessment Repair Needed In Progress Completed - Ready for Inspection Completed - Inspected No Repair Needed Other - See Comments

Repair Features
<ul style="list-style-type: none"> Stream Crossing Resource Location Repair Location Dozer Push Culvert

0 0.25 0.5 1 Miles

MD 1983 UTM Zone 10N Contour Interval: 80 ft.

Repair - BR V North
 Sept 16, 2023

Repair - BR V North
 Sept 16, 2023