



# BRANCH XXX

Div M

Div O

Div R

Div T

TOWNSEND

## Suppression Repair BRANCH XXX North

Happy Camp Complex  
CA-KNF-007022

Sept 16, 2023

- |  |   |  |   |
|--|---|--|---|
| <ul style="list-style-type: none"> <li> Happy Camp Complex</li> <li> Contained Fire Edge</li> <li> Uncontained Fire Edge</li> <li> Completed Dozer Line</li> <li> Completed Fuel Break</li> <li> Completed Hand Line</li> <li> Completed Road as Line</li> <li> Access or Improved Road</li> <li> Historical Dozer Line</li> </ul> | <ul style="list-style-type: none"> <li> Division Break</li> <li> Drop Point</li> <li> Staging Area</li> <li> Helispot</li> <li> Lookout</li> <li> Other</li> <li> Gate</li> <li> Other</li> <li> Water Source</li> <li> Gate</li> </ul> | <ul style="list-style-type: none"> <li> Forest Service Facility</li> <li> Campground</li> <li> Lookout - Permanent</li> <li> Highway</li> <li> Light Duty - Paved</li> <li> Light Duty - Gravel</li> <li> Light Duty - Dirt</li> <li> Unimproved</li> <li> Trail</li> <li> Footbridge</li> </ul> | <ul style="list-style-type: none"> <li> National Forest Admin. Boundary</li> <li> Ranger District Boundary</li> <li> Non-FS Lands w/in Forest Bdy.</li> <li> National Wild and Scenic River</li> <li> County</li> <li> Bureau of Indian Affairs</li> <li> Timber Lands - AKF</li> </ul> |
|--|---|--|---|

- | Repair Status                    | Repair Status                    |
|----------------------------------|----------------------------------|
| In Use - Fire Management         | In Use - Fire Management         |
| Needs Assessment                 | Needs Assessment                 |
| Repair Needed                    | Repair Needed                    |
| In Progress                      | In Progress                      |
| Completed - Ready for Inspection | Completed - Ready for Inspection |
| Completed - Inspected            | Completed - Inspected            |
| No Repair Needed                 | No Repair Needed                 |
| Other - See Comments             | Other - See Comments             |

- ### Repair Features
- Water Development or Draft Site
  - Stream Crossing
  - Resource Location
  - Repair Point
  - Dozer Push
  - Clean Up Area
  - Repair Line
  - Road Repair

0 0.25 0.5 1  
Miles

MD 1983 UTM Zone 10N  
Contour Interval: 80 ft.

Repair - BR XXX No. Sept 16, 2023

Repair - BR XXX No. Sept 16, 2023