



<ul style="list-style-type: none"> Happy Camp Complex Contained Fire Edge Uncontained Fire Edge Completed Dozer Line Completed Hand Line Completed Mixed Construction Line Completed Road as Line Other Access or Improved Road Historical Dozer Line 	<ul style="list-style-type: none"> Division Break Drop Point Camp Mobile Retardant Base Helispot Lookout Value at Risk Other Hazard Water Source Gate 	<ul style="list-style-type: none"> Ranger District Office Campground Trailhead Roadside Park Highway Light Duty - Paved Light Duty - Gravel Light Duty - Dirt Light Duty - Unspecified Composition Unimproved 	<ul style="list-style-type: none"> Trail Trail - Nat Rec/Scenic/Historic Footbridge National Forest Admin. Boundary Non-FS Lands w/in Forest Bdy. National Wild and Scenic River County Bureau of Indian Affairs State of California City
---	--	--	---

Suppression Repair
BRANCH V Middle
 Happy Camp Complex
 CA-KNF-007022
 Sept 17, 2023

Repair Status		Repair Status	
○ In Use - Fire Management	○ In Use - Fire Management	○ In Use - Fire Management	○ In Use - Fire Management
● Needs Assessment	● Needs Assessment	● Needs Assessment	● Needs Assessment
● Repair Needed	● Repair Needed	● Repair Needed	● Repair Needed
● In Progress	● In Progress	● In Progress	● In Progress
● Completed - Ready for Inspection	● Completed - Ready for Inspection	● Completed - Ready for Inspection	● Completed - Ready for Inspection
● Completed - Inspected	● Completed - Inspected	● Completed - Inspected	● Completed - Inspected
● No Repair Needed	● No Repair Needed	● No Repair Needed	● No Repair Needed
● Other - See Comments	● Other - See Comments	● Other - See Comments	● Other - See Comments

Repair Features	
Water Development or Draft Site	Structure Wrap
Stream Crossing	Retardant in Avoidance Area
Repair Point	Dozer Push
Culvert	Clean Up Area

Repair - BR V Middle
 Sept 17, 2023

Repair - BR V Middle
 Sept 17, 2023