



Repair - DTAG
Sept 18, 2023

<ul style="list-style-type: none"> Happy Camp Complex SRF Lightning Complex Contained Fire Edge Uncontained Fire Edge Division Break Drop Point Ranger District Office Campground 	<ul style="list-style-type: none"> Trailhead Roadside Park Lookout - Permanent Gate Highway Light Duty - Paved Light Duty - Gravel Light Duty - Dirt 	<ul style="list-style-type: none"> Light Duty - Unspecified Composition Unimproved Trail - Nat Rec/Scenic/Historic Ranger District Boundary Wilderness Area National Wild and Scenic River County Non-FS Lands w/in Forest Bdy. National Forest Admin. Boundary 	<ul style="list-style-type: none"> Bureau of Indian Affairs State of California City The Nature Conservancy <all other values> Timber Lands - AKF Timber Lands - Ecotrust Forest Management 	<ul style="list-style-type: none"> DTAG Features DTAG Road Landing or Log Deck Hazard Tree
---	--	--	---	--

Suppression Repair Danger Tree Abatement Group

Happy Camp Complex
CA-KNF-007022
Sept 18, 2023

DTAG Repair Status - Points

- In Use - Fire Management
- Needs Assessment
- Repair Needed
- In Progress
- Completed - Ready for Inspection
- Completed - Inspected
- No Repair Needed
- Other - See Comments

DTAG Repair Status - Roads

- In Use - Fire Management
- Needs Assessment
- Repair Needed
- In Progress
- Completed - Ready for Inspection
- Completed - Inspected
- No Repair Needed
- Other - See Comments

DTAG Cult. Clearance - Points

- CULS Survey Needed
- CULS Cleared

DTAG Cult. Clearance - Roads

- CULS Survey Needed
- CULS Cleared

Repair Status	DTAG Roads (miles)	Hazard Trees	Landings/Log Decks
TOTAL	64.1	20	102
Completed	0	0	0
In Progress	0	0	0
Repair Needed	64.1	20	102
No Repair Needed	0	0	0

0 0.5 1 2 Miles

NAD 1983 UTM Zone 10N Contour Interval: 400 ft.

Repair - DTAG
Sept 18, 2023