



<ul style="list-style-type: none"> Happy Camp Complex Smith River Complex SRF Lightning Complex Other 2023 Fires > 10 Contained Fire Uncountained Fire Edge Completed Dozer Line Completed Fuel Break 	<ul style="list-style-type: none"> Completed Hand Line Completed Mixed Construction Line Completed Road as Line Other Access or Improved Road Division Break Branch Break Drop Point 	<ul style="list-style-type: none"> Camp Staging Area Dip Site Mobile Retardant Base Helibase Sling Site Unimproved Landing Area 	<ul style="list-style-type: none"> Lookout Value at Risk Other Gate Hazard Water Source Gate Ranger District Office 	<ul style="list-style-type: none"> Forest Service Facility Campground Picnic Area Trailhead Roadside Park Lookout - Permanent Highway Light Duty - Paved 	<ul style="list-style-type: none"> Light Duty - Gravel Light Duty - Dirt Light Duty - Unspecified Composition Unimproved Trail Trail - Nat Rec/ Scenic/Historic Footbridge 	<ul style="list-style-type: none"> National Forest Admin. Boundary Ranger District Boundary Non-FS Lands w/in Forest Bdy. Wilderness Area National Wild and Scenic River National Rec/ Scenic Area County 	<ul style="list-style-type: none"> Bureau of Land Management Bureau of Indian Affairs State of California City The Nature Conservancy Timber Lands - Ecotrust Forest Management Timber Lands - AKF
--	--	--	---	--	---	--	---

Suppression Repair OVERVIEW

Happy Camp Complex CA-KNF-007022

Sept 18, 2023

EVENT Point - Repair Status	EVENT Line - Repair Status
○ In Use - Fire Management	— In Use - Fire Management
● Needs Assessment	— Needs Assessment
● Repair Needed	— Repair Needed
● In Progress	— In Progress
● Completed - Ready for Inspection	— Completed - Ready for Inspection
● Completed - Inspected	— Completed - Inspected
● No Repair Needed	— No Repair Needed
● Other - See Comments	— Other - See Comments

Repair Features
■ Water Development or Draft Site
■ Structure Wrap
■ Stream Crossing
■ Road Repair
■ Retardant in Avoidance Area
■ Resource Location
● Repair Point
■ Dozer Push
■ Culvert
■ Clean Up Area
■ Repair Line
— Road Repair

NAD 1983 UTM Zone 10N Contour Interval: 400 ft.

Repair - Overview
Sept 18, 2023

Repair - Overview
Sept 18, 2023