



Repair - Overview		Repair - Overview		Repair - Overview		Repair - Overview		Repair - Overview	
Happy Camp Complex	Completed Hand Line	Camp	Value at Risk	Gate	Light Duty - Paved	National Forest	Bureau of Indian Affairs	In Use - Fire Management	Water Development or Draft Site
Smith River Complex	Completed Mixed Construction Line	Staging Area	Other	Ranger District Office	Light Duty - Gravel	Ranger District Boundary	State of California	Needs Assessment	Structure Wrap
SRF Lightning Complex	Completed Road as Line	Dip Site	Gate	Forest Service Facility	Light Duty - Dirt	Non-FS Lands win Forest Bdy	City	Repair Needed	Stream Crossing
Other 2023 Fires > 10	Other	Mobile Retardant Base	Bridge	Campground	Light Duty - Unspecified Composition	Wilderness Area	The Nature Conservancy	In Progress	Road Repair
Contained Fire	Access or Improved Road	Helibase	Internet Access	Picnic Area	Unimproved Road	National Wild and Scenic River	Timber Lands - Ecotrust Forest Management	Completed - Ready for Inspection	Retardant in Avoidance Area
Uncounted Fire Edge	Aerial Hazard	Sling Site	Repeater	Trailhead	Trail	National Rec/ Scenic Area	Timber Lands - AKF	Completed - Inspected	Resource Location
Completed Dozer Line	Division Break	Unimproved Landing Area	Hazard	Roadside Park	Trail - Net Rec/ Scenic/Historic	County	Bureau of Land Management	No Repair Needed	Repair Line
Completed Fuel Break	Branch Break	Lookout	Water Source	Roadside Park Lookout/Permanent	Footbridge	Highway		Clean Up Area	Road Repair
Drop Point		Restricted Water Source						Repair Point	
								Dozer Push	
								Culvert	
								Clean Up Area	

Suppression Repair OVERVIEW

Happy Camp Complex
CA-KNF-007022
Sept 19, 2023

EVENT Point - Repair Status	EVENT Line - Repair Status
In Use - Fire Management	In Use - Fire Management
Needs Assessment	Needs Assessment
Repair Needed	Repair Needed
In Progress	In Progress
Completed - Ready for Inspection	Completed - Ready for Inspection
Completed - Inspected	Completed - Inspected
No Repair Needed	No Repair Needed
Other - See Comments	Other - See Comments

Repair Features
Water Development or Draft Site
Structure Wrap
Stream Crossing
Road Repair
Retardant in Avoidance Area
Resource Location
Repair Point
Dozer Push
Culvert
Clean Up Area
Repair Line
Road Repair

0 0.5 1 2 3 4 Miles

NAD 1983 UTM Zone 10N Contour Interval: 400 ft.

Repair - Overview
Sept 19, 2023