0


S

1

ш

Y

## REPAIR OVERVIEW South Fork Complex September 11, 2023 DIV O **DIV F** DIV W



Unimproved Landing Area

EATON PRAIRIE

SUICIDE ROCK

Staging Area Lookout

123°39'0"W

■ Value at Risk Other Landmark **11** Bridge Water Development or Draft Site

Landing or Log Deck

Stream Crossing Road Repair Retardant in Avoidance Area Repair Point

Repeater Hazard Water Source Restricted Water Source

123°35'0"W

Fence - Cut/Damaged

Dozer Push

Clean Up Area

Internet Access


Culvert

In Use - Fire Management Needs Assessment Repair Needed In Progress

123°34'0"W

Completed - Inspected No Repair Needed Other - See Comments

Completed - Ready for Inspection Needs Assessment Repair Needed In Progress Completed - Ready for Inspection Completed - Inspected No Repair Needed In Use - Fire Management Other - See Comments



123°30'0"W