


# REPAIR OVERVIEW South Fork Complex September 12, 2023

REPAIR OVERVIEW CA-SHF-001004 September 12, 2023



0 0.3 0.6 1.1 1.7 2.2 Miles

<ul style="list-style-type: none"> <li> Dip Site</li> <li> Helisite</li> <li> Sling Site</li> <li> Unimproved Landing Area</li> <li> Division Break</li> <li> Drop Point</li> <li> Staging Area</li> <li> Lookout</li> <li> Value at Risk</li> <li> Other</li> <li> Landmark</li> <li> Bridge</li> <li> Water Development or Draft Site</li> </ul>	<ul style="list-style-type: none"> <li> Stream Crossing</li> <li> Road Repair</li> <li> Retardant in Avoidance Area</li> <li> Repair Point</li> <li> Landing or Log Deck</li> <li> Fence - Cut/Damaged</li> <li> Dozer Push</li> <li> Culvert</li> <li> Clean Up Area</li> <li> Internet Access</li> <li> Repeater</li> <li> Hazard</li> <li> Water Source</li> <li> Restricted Water Source</li> <li> In Use - Fire Management</li> <li> Needs Assessment</li> <li> Repair Needed</li> <li> In Progress</li> </ul>	<ul style="list-style-type: none"> <li> Completed - Ready for Inspection</li> <li> Completed - Inspected</li> <li> No Repair Needed</li> <li> Other - See Comments</li> <li> In Use - Fire Management</li> <li> Needs Assessment</li> <li> Repair Needed</li> <li> In Progress</li> <li> Completed - Ready for Inspection</li> <li> Completed - Inspected</li> <li> No Repair Needed</li> <li> Other - See Comments</li> </ul>
--	---	--

Datum: NAD 1983 UTM Zone 10N