






REPAIR OVERVIEW South Fork Complex September 14, 2023

REPAIR OVERVIEW CA-SHF-001004 September 14, 2023



<ul style="list-style-type: none"> Dip Site Helispot Sling Site Unimproved Landing Area Drop Point Staging Area Lookout 	<ul style="list-style-type: none"> Division Break Value at Risk Other Landmark Bridge Water Development or Draft Site 	<ul style="list-style-type: none"> Stream Crossing Road Repair Retardant in Avoidance Area Repair Point Landing or Log Deck Fence - Cut/Damaged Dozer Push Culvert Clean Up Area Internet Access 	<ul style="list-style-type: none"> Repeater Hazard Water Source Restricted Water Source In Use - Fire Management Needs Assessment Repair Needed In Progress 	<ul style="list-style-type: none"> Completed - Ready for Inspection Completed - Inspected No Repair Needed Other - See Comments In Use - Fire Management Needs Assessment Repair Needed In Progress Completed - Ready for Inspection Completed - Inspected No Repair Needed Other - See Comments
---	---	--	---	--

Datum: NAD 1983 UTM Zone 10N