


REPAIR OVERVIEW South Fork Complex September 19, 2023

REPAIR OVERVIEW CA-SHF-001004 September 19, 2023



		Accountable Property Pump Water Tank Dip Site Helipad	Slingshot Unimproved Landing Area Division Break Drop Point Staging Area	Lookout Value at Risk Other Landmark Bridge Water Development or Draft Site Stream Crossing	Road Repair Retardant in Avoidance Area Repair Point Landing or Log Deck Fence - Cut/Damaged Dozer Push	Culvert Clean Up Area Internet Access Repeater Hazard Water Source	Restricted Water Source NHDPoint FCCode Lake / Pond Stream/River Type	Stream/River Intermittent Road Class Local Roads Gravel Roads Dirt Roads Trails	Repair Status In Use - Fire Management Needs Assessment Repair Needed In Progress Completed - Ready for Inspection Completed - Inspected No Repair Needed	Other - See Comments Repair Status In Use - Fire Management Needs Assessment Repair Needed In Progress Completed - Ready for Inspection Completed - Inspected No Repair Needed
		0 0.3 0.6 1.1 1.7 2.2 Miles			Datum: NAD 1983 UTM Zone 10N					