


POD	Cabin	Repair	Uncontaminated	No Repair Needed
Clap Site	Pile Station	Safety Zone	In Use - Fire Management	Smith River CA Wildlife Preserve
Mobile Radiant Base	Bridge	Water Source	Need Assessment	Administrative FS Boundary
Highgate	Water Development or Draft Site	Hazard	Report Needed	Range District Boundary
Weather	Roadway Closure or Draft Site	Hazardous Waste Source	In Progress	Other Designated Boundary
Ship Site	Stream Crossing	Completed Fuel Break	Approved for Provisional USFS Boundary	Approved or Provisional USFS Boundary
Division Break	Intersect in Avoidance Area	Completed Road Construction Line	Need Assessment	Federal Wilderness Boundary
Branch Break	Approved Location	Completed Road as Line	Completed - Ready for Inspection	State Wilderness Area
Hazard	Repair Point	Access or Improved Road	Completed - Inspected	Research Natural Area
Incident Command Post	Landing or Log Deck	Highlighted Feature (Zone Break)	Other - See Comments	Area of Critical Environmental Concern
Drop Point	Hazard Tree	Rapid Line	In Use - Fire Management	Other Designated Boundary
Closure	Hazard Fuel	Road Repair	Report Needed	Land Management Boundary
Camp	Hazard Fuel	USFS Launch and Recovery Zone	In Progress	State Land
Staging Area	Hazard Fuel	Fire Stop (Fire Collector)	Completed - Ready for Inspection	POD/Repair/USFS Icon
Lookout	Open Top Area	Contained	Completed - Inspected	Federal Wilderness Boundary
Value at Risk	Other			
Landmark				

POD / REPAIR

Smith River Complex

CA-SRF-000968

10/02/2023



Smith River Complex
CA-SRF-000968

POD

10/02/2023