



DIV V

DIV S

DIV R

BRANCH V

SUPPRESSION REPAIR
BRANCH V
 Smith River Complex
 CA-SRF-000968

- Dip Site
- Heligap
- Division Break
- Branch Break
- Medical
- Incident Command Post
- Drip Point
- Closure
- Staging Area
- Value at Risk
- Other
- Gate
- Bridge
- Water Development or Draft Site
- Structure Wisp
- Stream Crossing
- Road Repair
- Retardant in Avoidance Area
- Resource Location
- Repair Point
- Hazard Tree
- Fence - C&D/Damaged
- Dropper Path
- Culvert
- Fire Edge (Field Collection)
- Contained
- In Use - Fire Management
- Needs Assessment
- Repair Needed
- Completed Mixed Construction Line
- Completed Road as Line
- Access or Improved Road
- Highlighted Feature (Zone Break)
- Other - See Comments
- In Use - Fire Management
- Needs Assessment
- Repair Needed
- In Progress
- Completed - Ready for Inspection
- Completed - Inspected
- No Repair Needed
- Other - See Comments
- Smith River Co Wildlife Perimeter
- Federal Wilderness Boundary



0 0.5 1 2 Miles
 1:25,000 NAD83 UTM 10N

Smith River Complex
 CA-SRF-000968
REPAIR
BRANCH V
 10/04/2023