


Suppression Repair Branch VIII



Smith River Complex North
CA-SRF-000968
10/05/2023

94,606 acres at 9/28/2023 @ 1940 PDT

North American 1983 Datum, Lat/Long Grid

- | | | | | | | | | | | |
|-----------------|-----------------------------------|-----------------------|----------------------------|------------------------------------|-------------------------------------|------------------------------------|-------------------------|--|-----------------------------|----------------------|
| ▲ Peaks | ● Other | ● Dozer Push | ● Restricted Water Source | ● Completed - Ready for Inspection | ▬ Completed Burnout | ▬ In Use - Fire Management | ▬ Completed - Inspected | ▬ ACEC - Primary Area of Environmental Concern | ▬ National Wilderness Areas | ▬ BIA, Tribal |
| ○ Helibase | ○ Bridge | ○ Culvert | ○ In Use - Fire Management | ▬ Completed - In Progress | ▬ Completed Mixed Construction Line | ▬ Needs Assessment | ▬ Other - See Comments | ▬ ACEC - Research Natural Area | ▬ City, County, Other | ▬ DOE, Other Federal |
| ○ Sling Site | ○ Water Development or Draft Site | ○ Mobile Weather Unit | ○ Needs Assessment | ▬ Completed - No Repair Needed | ▬ Completed Dozer Line | ▬ Repair Needed | ▬ Contained | ▬ State or Territory | ▬ State | ▬ DOD |
| ▬ Branch Break | ○ Road Repair | ○ Internet Access | ○ Repair Assessment | ▬ In Progress | ▬ Completed Fuel Break | ▬ In Progress | ▬ Uncontained | ▬ Trail | ▬ BLM | ▬ NPS |
| ▬ Drop Point | ○ Repair Point | ○ Repeater | ○ Repair Needed | ▬ Completed - Ready for Inspection | ▬ Completed Hand Line | ▬ Completed - Ready for Inspection | ▬ Botanical Areas | ▬ Forest Service | ▬ ANCSA/Private | ▬ BOR |
| ▬ Staging Area | ○ Landing or Log Deck | ○ Hazard | ○ In Progress | | ▬ Highlighted Feature | | | ▬ NPS | ▬ USFS | ▬ No Agency |
| ○ Value at Risk | ○ Water Source | | | | | | | ▬ Forest Service | ▬ USFS | |

