



- | | | | |
|--|---|--|---|
| <ul style="list-style-type: none"> ● Top Site ● Mobile Retardant Base ● Helipad ● Staging Site ● Branch Break ● Medical ● Incident Command Post ● Drop Point ● Closure ● Staging Area ● Lookout ● Value at Risk ● Landmark ● Gate ● Fire Station ● Bridge ● Water Development or Draft Site | <ul style="list-style-type: none"> ● Structure Wreck ● Stream Crossing ● Road Repair ● Retardant in Assistance Area ● Resource Location ● Repair Point ● Landing or Log Deck ● Hazard Tree ● Ditch Path ● Culvert ● Clean Up Area ● Mobile Weather Unit ● Internet Access ● Other ● Safety Zone ● Hazard ● Water Source ● Reestablished Water Source ● Completed Over Line | <ul style="list-style-type: none"> — Completed Fuel Break — Completed Hand Line — Completed Mixed Construction Line — Completed Road as Line — Access or Improved Road — Highlighted Feature (Zone Break) — Other — Repair Line — Fence - Cut/Damaged — UAG Launch and Recovery Zone — Fire Edge (Field Collection) — Uncontaminated — In Use - Fire Management ● Needs Assessment ● Repair Needed ● Repair Needed - Ready for Inspection ● Completed - Inspected ● Other - See Comments | <ul style="list-style-type: none"> ● In Use - Fire Management ● Needs Assessment ● Repair Needed ● In Progress ● Completed - Ready for Inspection ● Completed - Inspected ● Other - See Comments — Paved Road — Gravel Road — Primitive Road — Closed Roads — Local Road — OWD — Closed Road — Interstate — Highway — Local Connecting Road — Smith River Co. Wildlife Perimeter — Federal Wilderness Boundary |
|--|---|--|---|

SUPPRESSION REPAIR

Smith River Complex

CA-SRF-000968

10/09/2023



0 0.75 1.5 3 Miles

1:60,500 NAD83 UTM 10N

Smith River Complex
CA-SRF-000968

REPAIR

10/09/2023