


- | | | | | |
|-----------------|-----------------------|---------------------------|------------------------------------|-------------------------------------|
| ● Helispot | ● Repair Point | ⊗ Completed Dozer Line | ● Completed - Ready for Inspection | --- Closed Roads |
| ⊠ Closure | ● Landing or Log Deck | — Completed Hand Line | ● Repair Needed | — Local Road |
| ⊠ Staging Area | ● Hazard Tree | — Completed Road as Line | ● In Progress | — 4WD |
| ● Value at Risk | ● Fence - Cut/Damaged | — Access or Improved Road | ● Completed - Ready for Inspection | — Closed Road |
| ● Other | ● Dozer Push | — Contained | — Paved Road | — Highway |
| ● Bridge | ● Repeater | ● Repair Needed | — Gravel Road | — Smith River Cx Wildfire Perimeter |
| ● Road Repair | ● Hazard | ● In Progress | — Primitive Road | — Federal Wilderness Boundary |

NORTH SUPPRESSION REPAIR FOR SPRING

Smith River Complex
CA-SRF-000968

10/17/2023



Smith River Complex
CA-SRF-000968

REPAIR
BRANCH V, XX

10/17/2023