


- |               |                     |                         |                                  |                                   |
|---------------|---------------------|-------------------------|----------------------------------|-----------------------------------|
| Helispot      | Repair Point        | Completed Dozer Line    | Completed - Ready for Inspection | Closed Roads                      |
| Closure       | Landing or Log Deck | Completed Hand Line     | Repair Needed                    | Local Road                        |
| Staging Area  | Hazard Tree         | Completed Road as Line  | In Progress                      | 4WD                               |
| Value at Risk | Fence - Cut/Damaged | Access or Improved Road | Completed - Ready for Inspection | Closed Road                       |
| Other         | Dozer Push          | Contained               | Paved Road                       | Highway                           |
| Bridge        | Repeater            | Repair Needed           | Gravel Road                      | Smith River Cx Wildfire Perimeter |
| Road Repair   | Hazard              | In Progress             | Primitive Road                   | Federal Wilderness Boundary       |

### NORTH SUPPRESSION REPAIR FOR SPRING

Smith River Complex  
CA-SRF-000968

10/29/2023



Smith River Complex  
CA-SRF-000968  
**REPAIR**  
BRANCH V, XX  
10/29/2023