



- | | | | | |
|---------------------|------------------------|-------------------------------------|------------------------------------|-------------------------------------|
| ● Helispot | ● Repair Point | — Completed Mixed Construction Line | ● Completed - Ready for Inspection | — 4WD |
| ● Drop Point | ● Landing or Log Deck | — Completed Road as Line | ● Repair Needed | — Closed Road |
| ● Staging Area | ● Dozer Push | — Access or Improved Road | ● In Progress | — Highway |
| ● Value at Risk | ● Culvert | — Repair Line | — Paved Road | — Local Connecting Road |
| ● Other | ● Clean Up Area | — Contained | — Gravel Road | — Smith River Cx Wildfire Perimeter |
| ● Stream Crossing | ● Hazard | — Uncontained | — Primitive Road | — Federal Wilderness Boundary |
| ● Road Repair | ● Completed Dozer Line | ● Repair Needed | — Closed Roads | |
| ● Resource Location | ● Completed Hand Line | ● In Progress | — Local Road | |

SOUTH SUPPRESSION REPAIR FOR SPRING

Smith River Complex
CA-SRF-000968

10/29/2023



Smith River Complex
CA-SRF-000968
REPAIR
BRANCH V, XX
10/29/2023