



NORTH COAST Suppression Repair Overview
 2023 SRF Lightning Complex
 CA-SRF-000986
 10/16/2023 Day

Event Line - Repair Status		Event Point - Repair Status	
—	In Use - Fire Management	●	In Use - Fire Management
—	Needs Assessment	●	Needs Assessment
—	Repair Needed	●	Repair Needed
—	In Progress	●	In Progress
—	Completed - Ready for Inspection	●	Completed - Ready for Inspection
—	Completed - Inspected	●	Completed - Inspected
—	No Repair Needed	●	No Repair Needed
—	Other - See Comments	●	Other - See Comments
—	Strategic Repair Line	●	Other - See Comments

—	SRF Lighting Complex	—	Road Repair	●	Landing or Log Deck
—	Neighboring Complex	—	Branch Break	●	Hazard Tree
—	Wildfires	—	Incident Command Post	●	Dozer Push
—	Contained Fire Edge	—	Drop Point	●	Water Development or Draft Site
—	Uncontained Fire Edge	—	Closure	●	Structure Wrap
—	Completed Dozer Line	—	Staging Area	●	Stream Crossing
—	Completed Hand Line	—	Helispot	●	Road Repair
—	Completed Mixed	—	Unimproved Landing Area	●	Resource Location
—	Construction Line	—	Lookout	●	Repair Point
—	Completed Road as Line	—	Value at Risk		
—	Access or Improved Road				
—	Repair Line				

●	USFS Communication Site	—	Ranger District Boundary	—	Paved Road
●	Structure	—	Private Land within Forest	—	Gravel Road
●	Ranger District Office	—	Boundary	—	Dirt Road
●	CAMPGROUND	—	National Wilderness Area	—	Unimproved Road
●	TRAILHEAD	—	Wild and Scenic River	—	Trail
●	HORSE CAMP	—	Kanuk Tribe Federal Trust Land	—	Trail
●	Cemetery	—	Yurok Ownership	—	Trail
●	School (K-12)	—	Recreation Boundary	—	Trail
●	Post Office	—	County Boundary	—	Trail
●	Fire Station / EMS Station	—	Secondary Highway	—	Trail
●	Administrative Forest Boundary	—	Road, Unspecified		

Scale: 0 0.5 1 2 Miles
 NAD 1983 UTM Zone 10N
 80 ft. Contours