


# Lime Complex, Miners Fire Suppression Repair Map CA-SHF-1041

August 14, 2008



SCM T2 IMT Situation Unit  
August 13, 2008  
2201 Hours

### REPAIR FOR MINERS FIRE

- COMPLETED REPAIR
- FS GRADER
- Recontour
- Open Drainage
- Recontour
- Dozer
- Dozer, Open Drainage
- Dozer, Recontour
- Excavator, Open Drainage
- Excavator, Recontour
- Dozer
- No Rehab
- Waterbar
- Dozer, Breach Trench
- Dozer, Waterbar
- Excavator, Breach Trench
- Excavator, Pull in Berm
- Excavator, Waterbar
- Dozer, repair road

