


Lime Complex, Miners Fire Suppression Repair Map CA-SHF-1041

August 15, 2008



SCM T2 IMT Situation Unit
August 14, 2008
2153 Hours

REPAIR FOR MINERS FIRE

- COMPLETED REPAIR
- FS GRADER
- WATER TENDER
- Recontour
- Pull in Slash
- Dozer, repair road
- Open Drainage
- Recontour
- Dozer
- Dozer, Open Drainage
- Dozer, Recontour
- Excavator, Open Drainage
- Excavator, Recontour
- N/A, Waterbar
- Dozer
- No Rehab
- Waterbar
- Dozer, Breach Trench
- Dozer, Waterbar
- Excavator, Breach Trench
- Excavator, Pull in Berm
- Excavator, Waterbar

