


Lime Complex, Slide Fire Suppression Repair Map CA-SHF-1041


August 15, 2008



Scale T2 MT Situation Unit
August 14, 2008
1600 Hours

REPAIR FOR SLIDE FIRE

- COMPLETED REPAIR
- Previous restoration needing repair
- Equipment, recommendation**
- Excavator, Pull in Slash
- Excavator, Recontour
- Equipment, treatment**
- Excavator,
- Excavator, Open Drainage
- Excavator, Pull Fill
- Excavator, Pull Woody Back
- Equipment, recommendation**
- Dozer, Waterbar
- Excavator, Pull in Berm
- Excavator, Waterbar
- N/A, Waterbar



1:5,280