


# Lime Complex, Miners Fire Suppression Repair Map CA-SHF-1041


August 21, 2008



IMT Situation  
August 19, 2008  
1521 Hours

## REPAIR FOR MINERS FIRE

- COMPLETED REPAIR
- FS GRADER
- WATER TENDER
- Recontour
- Pull in Slash
- Open Drainage
- Recontour
- Dozer
- Dozer, Open Drainage
- Dozer, Recontour
- Excavator, Open Drainage
- Excavator, Recontour
- N/A, Waterbar
- Dozer
- No Rehab
- Waterbar
- Dozer, Breach Trench
- Dozer, Waterbar
- Excavator, Breach Trench
- Excavator, Pull in Berm
- Excavator, Waterbar
- Dozer, repair road



DIV O/P/Q

1:20,000

Mile Complex ICP