



South Division

East Branch



Live Dog Search	Cadaver Dog Search	Lowboy	Clear to Drive	Drop Point
Debris	Bridge	Car	Gas	Mud
Pile	Road	No Search	No Damage, Primary Complete	No Access, Primary Complete
Damaged, Primary Complete	Destroyed, Primary Complete	No Damage, Secondary Complete	Damaged, Secondary Complete	County Boundary
Assessor Parcels	Protective Action Zones	Fire Protection District	Power Transmission Lines	Pipelines

OPERATIONS MAP South 2018 XSB January Storms CA-MTO-18-000071



Scale: 1:3,600
NAD83

2018 XSB
January Storm
CA-MTO-18-000071
OPS MAP
South
Jan 13 2018