



**SUPPRESSION REPAIR MAP**  
**Thomas Incident**  
 CA VNC 103156  
 December 30th, 2017




**SUPPRESSION REPAIR MAP**  
**Thomas Incident**  
 CA VNC 103156  
 December 30th, 2017



**Repair point type (Count on map page)**

Bridge Damage (0)	Drop Point (7)	Lop and Scatter Trees (0)	Road Sign Damage (1)	Trail Damage (1)
Chipping Slash (17)	Equipment Found (0)	Meadow Damage (0)	Safety Zone (1)	Water Course Crossing (4)
Culvert Damage (2)	Fence Damage (33)	Noxious Weeds (1)	Sensing Plant Species (0)	Water Development Damage (0)
Dozer Push (1)	Gate Damage (0)	Other (6)	Sling Site (0)	Water Drafting Location (0)
Dozer on Road (0)	Hazard Tree (2)	Other Sensitive Resource (6)	Spring (0)	Waterbar Needed (12)
Dozer on Unauthorized Road (0)	Helispot (1)	Retardant in Avoidance Area (0)	Staging Area (1)	Wilderness Incursion (2)
Draft Site (0)	Incident Base (0)	Road Barrier (0)	Structure Wrap (0)	Suppression Repair Areas (3)
Road Repair Needed (19)		Road Barrier (0)		

**Repair Point Status (Count on map page)**

Completed - READ Approved (2)	Identified for Repair (108)
Completed - Ready for READ Inspection (0)	Identified for Repair - READ Presence Needed (6)
Do Not Repair (1)	In Progress (0)

**Repair line type (ID#s underlined)**

Completed Dozer Line (49)	H - Hand Line (7)
R - Road as Line (6)	Staging Area Boundary (0)
Trail (1)	Retardant (18)

**Repair line status (Count on map page)**

Completed - READ Approved (24)	Identified for Repair - READ Presence Needed (4)
Completed - Ready for READ Inspection (12)	In Progress (0)
Do Not Repair (3)	Other - see comments (0)
Identified for Repair (20)	

**SUPPRESSION REPAIR MAP**  
**Thomas Incident**  
 CA VNC 103156  
 December 30th, 2017

TILE: B2

TILE: B2