



SUPPRESSION REPAIR MAP
Thomas Incident
 CA VNC 103156
 December 30th, 2017




SUPPRESSION REPAIR MAP
Thomas Incident
 CA VNC 103156
 December 30th, 2017



Repair point type (Count on map page)

Bridge Damage (0)	Drop Point (8)	Lop and Scatter Trees (2)	Road Sign Damage (0)
Chipping Slash (11)	Equipment Found (0)	Meadow Damage (0)	Safety Zone (0)
Culvert Damage (2)	Fence Damage (18)	Noxious Weeds (0)	Sensitive Plant Species (0)
Dozer Push (0)	Gate Damage (1)	Other (2)	Sling Site (0)
Dozer on Road (0)	Hazard Tree (0)	Retardant in Avoidance Area (0)	Spring (0)
Dozer on Unauthorized Road (0)	HazMat Site (0)	Road Barrier (0)	Staging Area (3)
Draft Site (0)	Helispot (0)	Road Repair Needed (2)	Structure Wrap (0)
	Incident Base (0)		Trail Damage (0)

Repair Point Status (Count on map page)

Completed - READ Approved (0)	Identified for Repair (51)
Completed - Ready for READ Inspection (0)	Identified for Repair - READ Presence Needed (1)
Do Not Repair (0)	In Progress (0)

Repair line type (ID#s underlined)

Completed Dozer Line (58)	H - Hand Line (10)
R - Road as Line (0)	Staging Area Boundary (0)
Trail (0)	Waterbar Needed (0)
Retardant (3)	Wilderness Incursion (0)

Repair line status (Count on map page)

Completed - READ Approved (37)	Identified for Repair - READ Presence Needed (0)
Completed - Ready for READ Inspection (12)	In Progress (0)
Do Not Repair (5)	Other - see comments (0)
Identified for Repair (14)	

TILE: C1

SUPPRESSION REPAIR MAP
Thomas Incident
 CA VNC 103156
 December 30th, 2017

TILE: C1