


Whittier Suppression Repair CA-LBOR 001770 July 25, 2017 NE Quadrant



- Highway
- Road - Light Duty - Dirt
- Road - Light Duty - Paved
- Road - Light Duty - Unspecified Composition
- Road - Unimproved
- Trail
- Foot Trail

- | | | | |
|--|---|---|---|
| () Division | ⊕ Fence, Repair Needed | --- Repair Lines | --- Natural Barrier |
| --- Fixed Wing Retardant | ⬇ Gate, Repair Needed | ⊗ Dozer Line | ⊗ Dozer on Road |
| --- Rotor Retardant | ⊕ Helispot, Repair Needed | - - - - - Hand Line | ⬆ Repair Needed |
| ⬇ Downed Tree, Repair Needed | ⊕ Trails, Repair Needed | ⬆ Stage 1 Repair Complete | ⬆ Stage 2 Repair Complete |
| ⬆ Hazard Tree, Repair Needed | ⊕ Water Development & Draft Site, Repair Needed | --- Repair Approved | |
| ⊗ Dozer Line, Repair Needed | ⊗ Wildlife Habitat Concern | | |
| ● Drop Point, Repair Needed | | | |



Zulu Sling

Div. A

Santa Cruz Dip

DP-11

DP-15

Div. B

H-4

H-5

DP-21
(Gun Club DP)

DP-22