


Repair Status Point
- Completed - Inspected
- Completed - Ready for Inspection
- In Progress
- Repair Needed
- No Repair Needed
- Other - See Comments
- Unknown

Repair Status Line
- Completed - Inspected
- Completed - Ready for Inspection
- In Progress
- Repair Needed
- No Repair Needed
- Other - See Comments
- Unknown

- Bridge
- Camp
- Closure
- Culvert
- Dip Site
- Drop Point
- Dozer Push
- Fence - Cut/Damaged
- Gate
- Hazard
- Hazard Tree
- Helibase
- Helispot
- Landing or Log Deck
- Mobile Weather Unit
- Repair Point
- Repeater
- Road Repair
- Safety Zone
- Staging Area
- Stream Crossing
- Water Source
- Value at Risk
- Other
- Division Break
- Branch Break
- Contained Line
- Completed Dozer Line
- Completed Hand Line
- Road as Completed Line
- Access or Improved Road
- Line Break Completed
- Fire Break Planned or Incomplete
- Aerial Retardant Drop
- Ridge/Geographic Feature
- Repair Line
- Road Repair
- Other
- National Forest Boundary
- USDA Forest Service
- Private Lands within the Forest Boundary
- Bureau of Indian Affairs
- Bureau of Land Management
- CA Dept. of Fish and Wildlife
- Other State Lands

Branch XIX, Branch X, Branch XX, Branch XXIX, Branch XXV

0 0.5 1 2 Miles

Scale: 1:35,000

Name: NAD 1983 California Teale Albers

Contours 40 ft