



	<b>Repair Status Point</b>	Repair Needed	Completed - Inspected	No Repair Needed	Completed - Ready for Inspection	In Progress	Unknown
	<b>Repair Status Line</b>	Repair Needed	Completed - Inspected	No Repair Needed	Completed - Ready for Inspection	In Progress	Unknown
Camp	Dozer Push	Helibase	Repeater	Staging Area	Division Break	Completed Doser Line	Fire Break Planned or Incomplete
Culvert	Fence - Cut/Damaged	Helipod	Retardant/Mud Pit	Stream Crossing	Branch Break	Completed Hand Line	Aerial Retardant Drop
Dip Site	Gate	Mobile Weather Unit	Road Repair	Value at Risk	Contained Line	Road as Completed Line	Ridge/Geographic Feature
Drop Point	Hazard	Repair Point	Safety Zone	Other	Access or Improved Road	Repair Line	Other
Private Lands within the Forest Boundary	Bureau of Indian Affairs	Bureau of Land Management	Non-Profit Conservancies and Trusts	National Forest Boundary	USDA Forest Service	Other Federal Lands	

Scale: 1:35,000    Name: NAD 1983 California Teale Albers    Contours 40 ft

0    0.5    1    2 Miles

Page Number: 8