



	Repair Status Point	No Repair Needed	Repair Status Line	No Repair Needed	Drop Point	Internet Access	Water Source	Uncontrolled Fire Edge	Road as Completed Line	National Forest Boundary	National Park Service
Completed - Inspected	Unknown	Completed - Inspected	Repair Needed	Other - See Comments	Dozer Push	Repair Point	Division Break	Contained Line	Access or Improved Road	USDA Forest Service	
Repair Needed		Unknown		Gate	Spot Fire	Branch Break	Completed Dozer Line	Road Repair	Private Lands within the Forest Boundary		
		Structure Wrap		Helispot		H - Completed Hand Line					

Branch 1	2	3	4	5	6	7	8	9
Branch 2								
Branch 3								
Branch 4								
Branch 5								
Branch 6								
Branch 7								
Branch 8								
Branch 9								

0 0.5 1 2 Miles

Scale: 1:35,000 Name: NAD 1983 California Teale Albers

Contours 40 ft