


Branch XIX



	<b>Repair Status Point</b>	Repair Needed	Completed - Inspected	Completed - Ready for Inspection	In Progress	No Repair Needed	Other - See Comments	Unknown	<b>Repair Status Line</b>	Repair Needed	Completed - Inspected	Completed - Ready for Inspection	In Progress	No Repair Needed	Other - See Comments	Unknown			

Branch XIX	1	2	3
Branch X	4	5	Branch XX
Branch 6	7	8	
Branch 81	9		

0 0.5 1 2 Miles

Scale: 1:35,000 Name: NAD 1983 California Teale Albers

Contours 40 ft

Page Number: 2