



	Repair Status Point	Repair Needed	Completed - Inspected	Unknown	Dozer Push	Repair Point	Sling Site	Contained Line	Road as Completed Line	Aerial Retardant Drop	USDA Forest Service
Repair Needed	Completed - Inspected	No Repair Needed	Unknown	Drop Point	Fence - Cut/Damaged	Repeater	Stream Crossing	Completed Dozer Line	Access or Improved Road	Ridge/Geographic Feature	Private Lands within the Forest Boundary
Unknown	Completed - Ready for Inspection	Other - See Comments		Drop Point	Gate	Safety Zone	Water Development or Draft Site	Completed Hand Line	Fire Break Planned or Incomplete	National Forest Boundary	Non-Profit Conservancies and Trusts

Scale: 1:35,000
Contours 40 ft

Name: NAD 1983 California Teale Albers

Page Number: 9