

**DIV N**



**H-3 Blackrock**

**H-8**

**Blackrock Station**

**Troy Meadow Spike**

**SQF Complex**  
**SUPPRESSION REPAIR ZONE 1**  
 CA-SQF-002622  
 10/14/2020



Repair Status		Other - See Comments		Other	
<span style="color: green;">●</span>	Completed - Inspected	<span style="color: yellow;">●</span>	In Progress	<span style="color: red;">●</span>	Repair Needed
<span style="color: orange;">●</span>	Completed - Ready for Inspection	<span style="color: purple;">●</span>	Unknown	<span style="color: grey;">●</span>	Other - See Comments
<span style="color: red;">●</span>	Repair Needed	<span style="color: green;">●</span>	Completed - Inspected	<span style="color: purple;">●</span>	Unknown
<span style="color: green;">●</span>	In Use - Fire Management	<span style="color: red;">●</span>	Repair Needed	<span style="color: purple;">●</span>	Unknown
<span style="color: orange;">●</span>	Completed - Ready for Inspection	<span style="color: red;">●</span>	Repair Needed	<span style="color: purple;">●</span>	Unknown

Symbol	Description
A	Dip Site
a	Dozer Push
1	Completed Hand Line
2	Completed Hand Line
Y	Road as Completed Line
h	Lookout
h	Access or Improved Road
U	Repair Point
U	Road Repair
U	Structure Wrap
U	Water Source
n	Value at Risk
a	Other
○	Contained Line
○	Completed Dozer Line
○	Completed Hand Line
○	Access or Improved Road
○	Aerial Retardant Drop
○	Road Repair
○	Wild and Scenic River Corridor
○	Wilderness Area
○	FS
○	Private

167625 acres W/ Shotgun,  
 as of 10/13/2020, 1030 HRS

SUPPRESSION REPAIR

SUPPRESSION REPAIR