



SUPPRESSION REPAIR LLOYD MEADOWS FREEMAN CREEK



SUPPRESSION REPAIR Lloyd Meadows/Freeman Creek

SQF Complex
CA-SQF-002622
11/01/2020



170,165 acres,
as of 10/31/2020, 0800 HRS



Administrative Forest	In Progress	Repair Needed	Air Tanker Retardant	Repair Point	BLM
Wilderness Area	Repair Needed	No Repair Needed	Road Repair	BOR	FS
Wilderness Area	Other - See Comments	Unknown	Backcountry Structures	Safety Zone	FWS
Administrative Forest	Other - See Comments	Completed Dozer Line	Dip Site	Sling Site	NPS
Slate Mtn Botanical Area	Unknown	Completed Hand Line	Culvert	Stream Crossing	State
Repair Status	Completed - Inspected	Road as Completed Line	Drop Point	Water Source	Private
Completed - Inspected	In Use - Fire Management	Proposed Dozer Line	Dozer Push	Value at Risk	Wildfire Daily Fire Perimeter
In Use - Fire Management	Completed - Ready for Inspection	Planned Fire Line	Hazard	Other	Wildfire Daily Fire Perimeter
Completed - Ready for Inspection	In Progress	Aerial Retardant Drop	Helispot	BIA	Wildfire Daily Fire Perimeter
				Label Point	