



SUPPRESSION REPAIR PONDEROSA

11/04/2020




Administrative Forest	In Progress	Repair Needed	Drop Point	BLM
Wilderness Area	Repair Needed	No Repair Needed	Dozer Push	BOR
Administrative Forest	No Repair Needed	Other - See Comments	Air Tanker Retardant	FS
Slate Mtn Botanical Area	Other - See Comments	Unknown	Road Repair	FWS
Repair Status	Completed - Inspected	Contained Line	Other	NPS
In Use - Fire Management	Completed - Inspected	Completed Dozer Line	Backcountry Structures	State
In Use - Fire Management	In Use - Fire Management	Completed Hand Line	Dip Site	Private
Completed - Ready for Inspection	Completed - Ready for Inspection	Access or Improved Road	Bridge	Wildfire Daily Fire Perimeter
In Progress	In Progress	Proposed Dozer Line	Closure	Private
		Fire Break Planned or Incomplete	Gate	BIA
		Planned Fire Line	Mobile Weather Unit	
		Air Tanker Retardant	Repair Point	
		Road Repair	Safety Zone	
		Other	Stream Crossing	
		Backcountry Structures	Other	
		Dip Site	BIA	
		Bridge		
		Closure		

SUPPRESSION REPAIR
Ponderosa
 SQF Complex
 CA-SQF-002622
 11/04/2020



170,682 acres,
 as of 11/03/2020, 0900 HRS



1:7,000

Map Updated: 11/3/2020 7:16