



Administrative Forest	Completed - Ready for Inspection	In Progress	Access or Improved Road	Hazard Tree	Staging Area	BLM
Wilderness Area	In Progress	No Repair Needed	Proposed Dozer Line	Dip Site	Stream Crossing	BOR
Wilderness Area	Repair Needed	Other - See Comments	Fire Break Planned or Incomplete	Closure	Structure Wrap	FS
Administrative Forest	No Repair Needed	Unknown	Planned Fire Line	Culvert	Water Source	FWS
Slate Mtn Botanical Area	No Repair Needed	Unknown	Uncontrolled Fire Edge	Repair Point	Restricted Water Source	State
Other - See Comments	No Repair Needed	Unknown	Contained Line	Repeater	Water Development or Draft Site	Private
Contained Line	In Use - Fire Management	Completed - Inspected	Fence	Road Repair	Value at Risk	Private
Completed Dozer Line	In Use - Fire Management	Completed - Inspected	Road Repair	Monitored Fire Edge	Wildfire Daily Fire Perimeter	Private
Completed Hand Line	Completed - Ready for Inspection	Completed - Inspected	Road as Completed Line	Proposed Hand Line	Gate	Private
Road as Completed Line	Completed - Ready for Inspection	Completed - Inspected	Proposed Hand Line	Hazard	Other	Private
Proposed Hand Line	Completed - Ready for Inspection	Completed - Inspected	Hazard	Other	BIA	Private

SUPPRESSION REPAIR Grouse Valley/Mtn Home

SQF Complex
CA-SQF-002622
11/05/2020



170,866 acres,
as of 11/04/2020, 0900 HRS

