



Administrative Forest	In Progress	Repair Needed	Drop Point	Internet Access	Staging Area	BOR
Wilderness Area	Repair Needed	No Repair Needed	Dozer Push	Landmark	Stream Crossing	FS
Wilderness Area	No Repair Needed	Other - See Comments	Fence - Cut/Damaged	Mobile Weather Unit	Structure Wrap	FWS
Administrative Forest	Other - See Comments	Unknown	Gate	Repair Point	Water Source	NPS
State Mtn Botanical Area	Unknown	Contained Line	Hazard Tree	Repeater	Restricted Water Source	State
State Mtn Botanical Area	Completed - Inspected	Completed Dozer Line	Retardant/Mud Pit	Retardant in Avoidance Area	Value at Risk	Private
State Mtn Botanical Area	In Use - Fire Management	Road as Completed Line	Helispot	Safety Zone	Other	Wildfire Daily Fire Perimeter
State Mtn Botanical Area	Completed - Ready for Inspection	Access or Improved Road	Camp	Sling Site	BIA	Other
State Mtn Botanical Area	In Progress	Completed Flow Line	Culvert	Sling Site	BLM	Private
State Mtn Botanical Area	Completed - Ready for Inspection	Proposed Dozer Line				

SUPPRESSION REPAIR
North Ponderosa
 SQF Complex
 CA-SQF-002622
 11/05/2020



170,866 acres,
 as of 11/04/2020, 0900 HRS

0 0.25 0.5 0.75 1 Miles

1:15,000

Map Updated: 11/4/2020 7:47